

SECTION 4.05 GROUND MARSHALLING DIRECTIONS

START ENGINE



LEFT HAND POINTING TO
SPECIFIC AEROPLANE. RIGHT
HAND MOVING IN A CIRCULAR
MOTION AT HEAD LEVEL

MOVE AHEAD



ARMS A LITTLE TO ONE SIDE
MOVED REPEATEDLY
UPWARDS AND BACKWARDS

URNS



ARM POINTING TO DIRECTION OF TURN.
OTHER HAND MOVED UP AND BACK.
SPEED OF MOVEMENT SHOWS RATE OF
TURN.

SLOW DOWN



ARMS DOWN CLOSE TO SIDES
MOVED UP AND
DOWN SEVERAL TIMES

STOP



ARMS REPEATEDLY CROSSED OVER
HEAD. RAPIDITY OF ARM MOVEMENT
SHOWS THE URGENCY OF STOP

CUT ENGINE



HAND LEVEL WITH SHOULDER.
HAND MOVED RAPIDLY SIDEWAYS
ACROSS THE THROAT